Dewatering and Seismic Stability Evaluation, Southeast Corner of Kennecott Utah Copper South Impoundment (URS, 2006)

South Tailings Embankment, Southeast Corner Dewatering Review Report (AMEC, 2002)

Earthquake Scenario & Probabilistic Ground Shaking Maps for the Salt Lake City, Utah, Metropolitan Area (Wong et al. 2002, UGS Miscellaneous Publication 02-5)

East Slope Stability Evaluation Report (URSGWC, 1999)

South Slope Seismic Evaluation Report (URSGWC, 1999)

Geotechnical Evaluation Summary Report for December 17, 1999 State Engineer's Meeting (URSGWC, 1999)

Seismic Hazard Analyses for Kennecott, Letter Report (URSGWC, 2000)

Dewatering Design Report – Southeast Corner Seismic Upgrade Design (Woodward-Clyde Consultants, 1998)

Independent Analysis of Deformations, Southeast Corner Seismic Upgrade Design, Tailings Impoundment Modernization Project, Kennecott Utah Copper Corporation, Magna, Utah (AGRA, June 1998)

Alternatives Evaluation Report, Tailings Impoundment Modernization Project, Southeast Corner, Southeast Corner Seismic Upgrade (Woodward-Clyde Consultants, 1998)

Tailings Impoundment Modernization Project, Southeast Corner, Southeast Corner Seismic Upgrade Design, Geotechnical Site Characterization (Woodward-Clyde Consultants, 1997)

Summary of Supplemental Field Investigations, Technical Memorandum, Geotechnical Design of Dewatering Measures, Tailings Impoundment Modernization Project, Southeast Corner (Woodward-Clyde Consultants, 1996)

Design Basis Memorandum, Geotechnical Design of Dewatering Measures, Tailings Impoundment Modernization Project, Southeast Corner (Woodward-Clyde Consultants, 1996)

Summary of Geohydrologic Data Review, Technical Memorandum, Geotechnical Design of Dewatering Measures, Tailings Impoundment Modernization Project, Southeast Corner (Woodward-Clyde Consultants, 1996)

Summary of Geotechnical Data Review, Technical Memorandum, Geotechnical Design of Dewatering Measures, Tailings Impoundment Modernization Project, Southeast Corner (Woodward-Clyde Consultants, 1996)

Characterization of Whole Tailings: Attachment G2 to Appendix G: Abutments and Northeast Corner; Geotechnical Detailed Design Report (Woodward-Clyde Consultants, 1995)

Characterization of Decant Pond Clay: Attachment G 1 to Appendix G: Abutments and Northeast Corner; Geotechnical Detailed Design Report (Woodward-Clyde Consultants, 1995)

Summary of Southeast Corner Dewatering (Memorandum by J. Pilz, Kennecott, 1995)

Inundation Technical Memorandum , Kennecott Tailings Impoundment, Salt Lake County, Utah (Woodward-Clyde Consultants, 1994)

Seismic Hazard Evaluation, Kennecott Tailings Impoundment Modernization Project, Magna, Utah (Woodward-Clyde, 1994)

Instrumentation Installation Report (Klohn-Crippen Consultants, Ltd., 1993)

Kennecott Utah Copper – Southeast Corner Berm Design (Klohn Leonoff, June 1993)

SEC Modernization, Geotechnical Characterization (Klohn Leonoff, 1992)

Kennecott Utah Copper – Assessment of Vertical Pumping Wells (Klohn Leonoff , 1992)

Kennecott Utah Copper, Southeast Corner Modernization, Stepback Dike Design Report (Klohn Leonoff, June 1992)

Geotechnical Site Characterization Report, Tailings Impoundment Modernization Project, North Expansion (Woodward-Clyde Consultants, 1991)

Task 2 Supplemental Geotechnical Investigation, Southeast Corner, Existing Tailings Impoundment (Woodward-Clyde Consultants, 1991)

Magna Tailings Impoundment, Risk Update, Internal Wedge Study (Klohn Leonoff, May 1991)

Magna Tailings Impoundment, Risk Reduction - Southeast Corner, Assessment of Embankment Ground Improvement Options (Klohn Leonoff, May 1991)

Magna Tailings Impoundment, Risk Reduction - Southeast Corner, Assessment of Buffer Zone Option (Klohn Leonoff, May 1991)

KUCC Tailings: Influence of Soil Aging and Failure Mode (Klohn Leonoff, Feb 1991)

Summary of 1989 Field Investigation Report (Klohn Leonoff, 1990)

Kennecott – Reduction Study (Klohn Leonoff, 1989)

Geotechnical Evaluation of Tailings Impoundment (Klohn Leonoff, 1988)

Evaluation of Future Tailings Disposal, 50 years of Additional Disposal, Utah Copper Division (UCD) Tailings Pond Near Magna, Utah, Kennecott Minerals Company (Dames and Moore, August 1983)

2008 2007 2006 2005 2004 2003 2002 2001 2000 1999 1998 1997 1996 1995 1994 1993 1992 1991 1990 1989 1988 1987 1986 1985 1984 1983

Peripheral Dust Control System Installed

NEC Siphon Extension

SEC Standpipe Piezometer Installation & Monitoring

SEC Electronic Piezometer Installation & Monitoring

Horizontal Drains Installed

Horizontal Drains Operation

SEC Step Back Dikes - Transition Deposition Away from SEC

Jet Pump Dewatering Test

Soil Moisture Field Test

East Side Dewatering Wells

Current Dewatering Well Installation & Operation

East Side Step Back Dike

Trial Wick Drain Program

NEC Wick Drain Installation

SEC Wick Drain Installation - Final

Seismic Warning System

Transition to North Impoundment

Tailing Deposition on South Impoundment Ceases